From: <u>Don Edgington</u>

To: <u>Moore, Gary; Delgado, Paige</u>

Cc: Lara, Alex

Subject: FW: Revised C&D Profile + Analysis

Date: Thursday, November 29, 2018 9:30:33 AM

FYI. I sent an email to Pace asking if the existing composite samples in their possession can be used to run TCLP Pb only.

From: Alderete, Chris <CAlderete@republicservices.com>

Sent: Thursday, November 29, 2018 9:20 AM

To: Muegge, Cheryl < CMuegge@republicservices.com>; Don Edgington < d.edgington@erllc.com>

Cc: Evan Wortman <e.wortman@erllc.com> **Subject:** RE: Revised C&D Profile + Analysis

Don,

Per our phonecall, the total Lead results for both samples are near or above 30mg/kg which typically requires we obtain a TCLP test to confirm the results are below the hazardous threshold.

Let me know if I can provide any additional info.

Thank you for choosing Republic Services

Chris Alderete

Manufacturing and Environmental Services

PO Box 1139 / 2815 State Hwy 42 N, Kilgore, TX 75663

- e <u>calderete@republicservices.com</u>
- o 903.986-5335 c 903.952-0084
- w www.RepublicServices.com



We'll handle it from here."

From: Muegge, Cheryl

Sent: Thursday, November 29, 2018 9:01 AM

To: Don Edgington; Alderete, Chris

Cc: Evan Wortman

Subject: RE: Revised C&D Profile + Analysis

NOTE: corrected email address for Chris Alderete.

Don,

We will submit these documents for further review and advise on status as soon as possible.

Thank you,

Cheryl Muegge

Sales Coordinator - Special Waste

2815 State Hwy 42 N Kilgore, TX 75662

- e cmuegge@republicservices.com
- 0 903-986-5337
- w RepublicServices.com



We'll handle it from here."

From: Don Edgington < d.edgington@erllc.com > Sent: Thursday, November 29, 2018 7:46 AM

To: caldrete@republicservices.com; Muegge, Cheryl < cMuegge@republicservices.com;

Cc: Evan Wortman < <u>e.wortman@erllc.com</u>> **Subject:** Revised C&D Profile + Analysis

Note that (<u>d.edgington@erllc.com</u>) is an external email. Forward unfamiliar emails to <u>infosec.phishing@republicservices.com</u>

Good morning.

Per your request, we collected composite samples of the wood and concrete generated from demolition of the on-site building in Leonard, Texas.

Attached please find a modified profile listing the sample date and sample ID numbers along with the final laboratory report from Pace Labs.

Let me know if you have any questions or need any additional information.

Regards,

Don Edgington Response Manager F.J. Doyle Salvage Site

Confidentiality Warning: This e-mail and any attachments contain information intended only for the use of the individual or entity named above. If the reader of this e-mail is not the intended recipient or the employee or agent responsible for delivering it to the intended recipient, any dissemination, publication or copying of this e-mail is strictly prohibited. Although this email has been scanned for malware, the sender does not accept any responsibility for any loss, disruption or damage to your data or computer system that may occur while using data contained in, or transmitted with, this e-mail. If you have received this e-mail in error, please immediately notify by return e-mail. Thank you.